

EXPEDITED SPCC SETTLEMENT AGREEMENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 7, 901 N. 5th ST., KANSAS CITY, KANSAS 66101

03 AUG -6 PM 1:38

ENVIRONMENTAL PROTECTION AGENCY-REGION VII

REGIONAL HEARING CLERK

Facility Name: Fremont Department of Utilities

Location: P.O. Box 1468, 400 E. Military Ave,

Fremont, Nebraska 68025

Owner/Operator: Dennis-Yannone (Respondent)

On June 26, 2002, an authorized representative of the United States Environmental Protection Agency (EPA) conducted an inspection to determine compliance with the Oil Pollution Prevention (SPCC) regulations promulgated at 40 CFR Part 112 under Section 311(j) of the Clean Water Act (33 U.S.C. § 1321(j)) (the Act), and found that Respondent had violated regulations implementing Section 311(j) of the Act by failing to comply with the regulations as noted on the attached Spill Prevention Control and Countermeasure Inspection Findings, Alleged Violations, and Proposed Penalty Form (Form), which is hereby incorporated by reference. incorporated by reference.

If Respondent does not sign and return this Expedited Settlement as presented within 30 days of the date of its receipt, the proposed Expedited Settlement is withdrawn without prejudice to EPA's ability to file any other enforcement action for the violations identified in the Form.

This proceeding and the Expedited Settlement are under the authority vested in the Administrator of EPA by Section 311(b) (6) (B) (i) of the Act, 33 U.S.C. § 1321(b) (6) (B) (i), as amended by the Oil Pollution Act of 1990, and 40 CFR §§ 22.13(b) and 22.18(b), published at 64 Fed. Reg. 40137 on July 23, 1999. The parties enter into this Expedited Settlement in order to settle the civil violations described in the Form for a penalty of \$1400.00. This settlement is subject to the following terms and conditions:

EPA finds that Respondent is subject to the SPCC regulations, which are published at 40 CFR Part 112, and has violated the regulations as further described in the Form. Respondent admits that he/she is subject to 40 CFR Part 112 and that EPA has jurisdiction over Respondent and Respondent's conduct as described in the Form. Respondent does not center the Inspection Findings and waives any Respondent's conduct as described in the Form. Respondent does not contest the Inspection Findings, and waives any objections it may have to EPA's jurisdiction. Respondent consents to the assessment of the penalty stated above. Respondent certifies, subject to civil and criminal penalties for making a false submission to the United States Government, that the violations have been corrected and Respondent has sent a certified check in the amount of \$1400.00 payable to the "Oil Spill Liability Trust Fund," to: "Rogional Hearing Clerk, Office of Regional Counsel, U.S. Environmental Protection Agency, 901 N. 5th Street, Kansas City, Kansas 66101". Respondent has noted on the penalty payment check "CWA-07-2003-0178" and the docket number of this case. number of this case.

DOCKET NO: CWA-07-2003-0178

This Expedited Settlement resolves Respondent's liability for Federal civil penalties for the violations of the SPCC regulations described in the Form. However, EPA does not waive any rights to take any enforcement action for any other past, present, or future violations by Respondent of the SPCC regulations or of any other federal statute or regulations. By its first signature, EPA ratifies the Inspection Findings and Alleged Violations set forth in the Form.

Upon signing and returning this Expedited Settlement to EPA, Respondent waives the opportunity for a hearing or appeal pursuant to Section 311 of the Act, and consents to EPA's approval of the Expedited Settlement without further

This Expedited Settlement is binding on the parties signing below, and is effective upon the Regional Judicial Officer's signature.

APPROVED BY EPA:

Date: Chief, Emergency Planning & Response Branch, Superfund. Division

APPROVED BY RESPONDENT:

Name (print): DERRIL MARSHALL

Title (print): GENERAL MANAGER

Date Angust 6, 200

INSTRUCTIONS ON REVERSE

Spill Prevention Control and Countermeasure Inspection Findings, Alleged Violations, and Proposed Penalty Form

(Note: Do not use this form if there is no secondary containment)

These Findings, Alleged Violations and Penalties are issued by EPA Region 7 under the authority vested in the Administrator of EPA by Section 311(b)(6)(B)(i) of the Clean Water Act, as amended by the Oil Pollution Act of 1990

Company Name			Docket Number: CWA									_								
	· · · · · ·			7	_	2 0	0	3	_	- 0	1	Ι,	7	8		9			• 5	
Facility Name			7 - 2 0 0 3 - 0 1 7 8 Date June 26, 2002																	
Fremont Department of Utilities			June 26, 2002																	
Address			Inspection Number																	
P	O Box 14	58		F	Y	- I	N	s	I	P -	0	[:	2	-	0)				
C	ity:			Inspector's Name:																
F	remont			Marc Callaghan																
State: Zip Code:			EPA Approving Official:																	
Ν	E	68025		Во	b Jac	ckson														7
Fa	acility Cor	itact:		Enforcement Contacts:											d					
Dennis Yannone			Bob Webber Phone Number: (913)551-7251 Alan Hancock Phone Number: (913)551-7647																	
· · · ·	(When t	GENERAL TOPICS: 11 he SPCC Plan review penalty exce			~	Facilion 12.5(a) enter), (c	e); e r	112 nax	.7 (l imu	b), m :	, (c all	e), .ov	(d) vab	le oi	f\$1,	.000	00.)	
	No Spi	ll Prevention Control and Counter	meas	ure F	Plan											. ,		. \$1	,000	0.00
X		ot certified by a professional engin																	-	
X		nagement approval of plan																		
		ot available for review																		
X		ot maintained on site (applies if fac																		
	No evidence of three-year review of plan by owner/operator																			
		ment(s) not certified by a professi																		
		ate or no prediction of equipment																		
X		pes not discuss appropriate contain																		
		.1 1							٠, ٩	~qui	Pirit	,11¢	•	٠.		• • •	• • •		TOC	<i></i> 00

Cla	iming installation of appropriate containment/diversionary structures is impractical but:
	No contingency plan\$100.00
	No written commitment of manpower, equipment, and materials
_	Written Procedures and Inspection Records 112.7(e)(8)
	Inspections required by 40 CFR Part 112 are not in accordance with written procedures developed for the facility
	Written procedures and a record of inspections are not signed by facility supervisor
	Written procedures and a record of inspections are not made part of the plan50.00
X	Written procedures and a record of inspections are not maintained for three years
	Personnel Training and Spill Prevention Procedures 112.7(e)(10)
	No training on the operation and maintenance of equipment to prevent discharges50.00
	No training on the applicable laws, rules, and regulations
	No designated person responsible for spill prevention
	Spill prevention briefings are not scheduled and conducted periodically
	Plan has inadequate or no discussion of personnel training and spill prevention procedures 50.00
	FACILITY DRAINAGE, ONSHORE (excluding Production Facilities) 112.7(e)(1)
	Valves used to drain diked areas are not of manual, open-and-closed design (note: flapper-type valves should not be used)
	Pumps or ejectors not manually activated when diked storage areas drained
	Drainage from undiked areas not into ponds, lagoons, or catchment basins, or no diversion systems to return spills to the facility
X	Plan has inadequate or no discussion of facility drainage
	BULK STORAGE TANKS (excluding Production Facilities) 112.7(e)(2)
	Material and construction of tanks not compatible to the material stored and the conditions of storage such as pressure and temperature
	Secondary containment appears to be grossly inadequate
	Materials of construction are not sufficiently impervious
	Excessive vegetation which affects the integrity of the containment system
	Walls of containment system are slightly eroded or have low areas

Wh	en dramage from diked areas is to a storm drain, open water course, or lake or pond:
	Bypass valve not normally sealed closed
	Runoff rain water not inspected and/or will cause a harmful discharge as defined in 40 CFR 110 300.00
	Bypass valve is not opened and resealed under responsible supervision
	Adequate records of drainage events are not maintained
	Underground tanks are not protected from corrosion or are not subjected to regular pressure testing 100.00
	Partially buried tanks do not have buried sections protected from corrosion
	Aboveground tanks not subject to periodic integrity testing, such as visual, hydrostatic, and nondestructive methods, etc
	Outside of tank not frequently observed for signs of deterioration, leaks which might cause a spill, or accumulation of oil inside diked area
	Steam return /exhaust of internal heating coils which discharge into an open water course not monitored, passed through a settling tank, skimmer, or other separation system
	Records of inspections of aboveground tanks are not maintained
	Tanks are not "fail-safe" engineered:
	No audible or visual high liquid level alarm, or
	No high-level pump cutoff devices set to stop flow at a predetermined tank content level, or 300.00
	No direct communications between tank gauger and pumping station, or
	No fast response system for determining liquid levels, such as computers, telepulse or direct vision gauges
	No testing of liquid level sensing devices to ensure proper operation
	Disposal facilities which discharge plant effluents directly to navigable waters are not monitored frequently to detect oil spills
\mathbf{X}	Visible oil leaks resulting in accumulations of oil in diked areas are not promptly corrected 300.00
	Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding
	Secondary containment inadequate for mobile or portable storage tanks
	Plan has inadequate or no discussion of bulk storage tanks
FAC	ILITY TRANSFER OPERATIONS, PUMPING, AND IN-PLANT PROCESSES, ONSHORE (excluding Production Facilities) 112.7(e)(3)
	Buried piping not corrosion protected with protective wrapping, coating, or cathodic protection 100.00
	Corrective action not taken on buried piping when corrosion damage found
	Terminal connections at transfer points on not-in-service or standby pipelines are not capped or blank-flanged and marked as to origin

Addie	ional Violations that must be corrected.
	Plan has inadequate or no discussion of facility security
	Facility lighting not commensurate with the type and location of facility to facilitate the discovery of spills during hours of darkness and to deter vandalism
	Loading and unloading connection(s) of pipelines are not capped or blank-flanged when not in service. 50.00
	Starter controls on pumps are not locked in the "off" position or located at a site accessible only to authorized personnel when pumps are not in a non-operating or standby status
X	Master flow and drain valves that permit direct outward flow of tank's contents to the surface are not secured in closed position when in a non-operating or standby status
	Facility not fully fenced and entrance gates are not locked and/or guarded when plant is unattended or not in production
SEC	URITY (excluding Production Facilities) 112.7(e)(9)
	Plan has inadequate or no discussion of facility tank car and tank truck loading/unloading rack 50.00
	There is no inspection of lowermost drains and all outlets prior to filling and departure of any tank car or tank truck
	There is no interlocked warning light, physical barrier system, or warning signs to prevent vehicular departure before complete disconnect from transfer lines
	Containment system does not hold at least the maximum capacity of the largest single compartment of any tank car or tank truck
	Inadequate secondary containment, and/or rack drainage does not flow to catchment basin, treatment system, or quick drainage system
FAC	ILITY TANK CAR AND TANK TRUCK LOADING/UNLOADING RACK, ONSHORE 112.7(e)(4)
	Plan has inadequate or no discussion of facility transfer operations, pumping, and in-plant processes 50.00
	Vehicle traffic not warned verbally or by appropriate signs of aboveground piping
	Periodic pressure testing of the valves and pipelines is not conducted
	Aboveground valves and pipelines are not inspected regularly
	Pipe supports are not properly designed to minimize abrasion and corrosion, and allow for expansion and contraction

- Complete copy of SPCC Plan shall be maintained at facility if the facility is normally attended at least 8 hours per day, or at the nearest field office if the facility is not so attended, and shall be made available to inspectors for on-site review during normal working hours.

Additional Comment: SPCC Plan will need to be revised to meet the July 17, 2002, final rule. Refer to www.epa.gov/oilspill for additional information.

⁻ The SPCC Plan shall be a carefully thought-out plan, prepared in accordance with good engineering practices. The complete SPCC Plan shall follow the sequence outlined in 40 CFR 112.7, and include a discussion of the facility's conformance with the appropriate guidelines listed.

IN THE MATTER OF Fremont Department of Utilities, Respondent Docket No. CWA-07-2003-0178

CERTIFICATE OF SERVICE

I certify that the foregoing Expedited SPCC Settlement Agreement was sent this day in the following manner to the addressees:

Copy hand delivered to Attorney for Complainant:

Kristina Kemp Assistant Regional Counsel Region VII United States Environmental Protection Agency 901 N. 5th Street Kansas City, Kansas 66101

Copy by Certified Mail Return Receipt to:

Fremont Department of Utilities P.O. Box 1468 400 E. Military Ave Fremont, Nebraska 68025

Copy by First Class Mail to:

US. Coast Guard Finance Center (OGR) 1430A Kristina Way Chesapeake, VA 23326

Dated: 8/7/03

Kathy Robinson

Regional Hearing Clerk